

Page 35 – Remove arrow from (1/8" Ply over to filler) in two places...

Arrow to plywood fitting bearer remains... Change root fitting extension past spar from 2 3/4" to 2" in (2) places on right side of page...

Page 36 – The distance between wing fittings is 1 1/8" ...

Page 37A – There are 2 compression braces on (both) sides of the called out truss ribs... Leonard says that wings built this way are good and need not be changed BUT he has opened the cover on both LE and XL prototype planes and finds that the compression braces are two strips placed on (one) side of the called out truss ribs... Therefore XL plan pages 36, 37 and 37A included below are revised and should be placed in your plans... Leonard says, "now to mend the cover" on my planes...

Page 51 – Use (1.5) mm plywood 1 1/4" strips...

Put these revised pages below in your plan set: